

Care and Maintenance

Wellmade's HardMax™ finish is among the industry's most durable flooring surfaces. Even so, regular care and maintenance will ensure many years of enjoyment while protecting your flooring investment.



- Sweep, vacuum or dust mop
- Wipe up spills immediately with a damp cloth
- Mop floors regularly with a cleaner recommended for hardwood floors
- Use area rugs at all exterior entrances
- Felt pads are recommended on the bases of chairs, tables and heavy furniture
- Never slide heavy furniture over floors